



गेल (इण्डिया) लिमिटेड

भारत सरकार का उपक्रम-महारत्न कंपनी)

GAIL (India) Limited

(A Govt. of India Undertaking- A Maharatna Company)

पोस्ट: गेल कॉम्पलेक्स, विजयपुर

जिला गुना (म.प्र.)- 473112

P.O.: GAIL COMPLEX, VIJAIPUR

DISTT.- GUNA (M.P.) - 473112

फोन/PHONE : +917544 274444,

फैक्स/FAX: +917544 274600

info@gail.co.in

REF NO : GAIL/VJA/CIVIL/SSSVV/2024/11/01

Date. 06.11.2024

TO WHOM IT MAY CONCERN

The Structural Audit of the building of Sri Satya Sai Vidya Vihar GAIL, Vijaipur is located in phase-2, GAIL Township, Vijaipur, Dist. Guna, M.P. has been carried out dated 30.07.2024 by M/s B.J. MEHTA ARCHITECTURAL & STRUCTURAL CONSULTANTS PVT LTD Auditor Name: MR. BAKULESH J. MEHTA, Licence No. : STR/M/65.

The report is being issued on the request vide mail dated 21/09/2024 from Principal, Sri Sathya Sai Vidya Vihar, GAIL has been annexed as for your reference.

Thanking you,

Yours truly,

Rajiv Khurana
Dy. General Manager (Civil)

CC:

- GM(Civil), GAIL Vijaipur
- GM (HR), GAIL, Vijaipur

PRINCIPAL

Sri Sathya Sai Vidya Vihar
GAIL Complex, Vijaipur
Distt. GUNA (M.P.)

पंजीकृत कार्यालय

गेल भवन, 16 भीकाजी कामा प्लेस

नई दिल्ली -110066, इंडिया

REGD. OFFICE:

GAIL BHAWAN, 16 BHIKAJI CAMA PLACE
NEW DELHI - 110066, INDIA

सीआईएन/CIN

L40200DL1984GOI018976

www.gailonline.com

Certificate of Stability

1	Name of clients	GAIL INDIA LIMITED
2	Name of structure	SRI SATHYA SAI VIDYA VIHAR SCHOOL
3	Village, town and district in which the factory is situated	AT PHASE -II TOWNSHIP AT GAIL VIJAIPUR, MADHYA PRADESH.
4	Full Postal address of structure	AT PHASE -II TOWNSHIP AT GAIL VIJAIPUR, MADHYA PRADESH.
5	Name of the occupier of the structure	GAIL (India) Limited
6	Name of manufacturing process to be carried on in the plant	Gas
7	Number of floors on which workers will be employed	Sri Sathya Sai Vidya Vihar School (Ground +1 upper floor).

I hereby state that I had inspected the above referred building with a view to carry out Structural Audit of the building. The observations have been recorded in Structural Audit report.

I have also carried out number of Non-Destructive Tests to estimate the present strength of concrete, the deterioration of the concrete strength and the level of loss of strength in steel resulting into distress.

Based on above, I have worked out a system for correcting the distress of the structure and providing necessary strengthening measures which is highlighted in Structural Audit report and the same is self explanatory.

I further state & issue a provisional stability certificate for the above-mentioned structure upon you carrying out all the suggested structural and allied repair works as per prescribed applicable standards and codes, rules, regulations and stipulations and with approved brands of materials and construction chemicals and ensuring good quality workmanship of accepted standards immediately.

Date : 30/07/2024

FOR B. J. MEHTA ARCHITECTURAL & STRUCTURAL CONSULTANTS PVT. LTD.

(B. J. MEHTA.)
DIRECTOR

Atulish
WZ

PRINCIPAL

05/BJM/RP/1867/GAIL PHASE II SSVV SCHOOL, VIJAIPUR, MADHYA PRADESH.
Sri Sathya Sai Vidya Vihar
GAIL Complex, Vijaipur
Distt. GUNA (M.P.)

